


ContactScope
3.CS210P02.V1A.E/A.24
1047147A

10




Input / Output
Machine interface
for GAP/Crash/Dress signal
Sub-D socket 37-way

Cable
7-way, 10m
3.710BS
1012656A

20

Optional sensors:

- 30a
- 30b
- 30c with 31



AE-GAP/Crash/Dress sensor
ROTOR
3.ASM.R.04
1013528A

31

AE-GAP/Crash/Dress sensor
STATOR
7-way, 3m
3.ASM.S1.03
1016049A

30c

Grinding spindle

Grinding spindle

AE-GAP/Crash/Dress sensor
Fluidsensor
7-way, 3m
3.FS.02.03
1016704A

30a

Workpiece support

30b

AE-GAP/Crash/Dress sensor
7-way, 3m
3.ASK.09.03
1015994A

Measuring jet directed to
the workpiece

Workpiece

Branch from the existing coolant jet of
the grinding machine